




H.E.R.S. Inspection Report

John Doe

Inspection Details

Date/Time: 2017-08-05 12:00:15
Street Address: 12345 Example St
Cityville, CA 91234
Climate Zone: 8
Phone Number: 310-123-4567
Scope of Work: New Furnace, New Condenser, New Coil, New Duct System

Overall Result: PASS



Furnace Details

Furnace #1

Furnace #2

Furnace #3

Make: Lennox
Location: Attic
BTUs: 70000
Filter: Return Mounted



Air Conditioner Details

Air Conditioner #1

Air Conditioner #2

Air Conditioner #3

Make:	Lennox
Tonnage:	3
Refrigerant:	R-410A



Duct Leakage

	<u>System #1</u>	<u>System #2</u>	<u>System #3</u>
Was this required?:	Yes		
Target Duct Leakage:	5% (New)		
Leakage CFM:	33		
Leakage %:	Heating: 2.0% Cooling: 2.8%		
Overall Result:	PASS		



Refrigerant Charge

	<u>System #1</u>	<u>System #2</u>	<u>System #3</u>
Was this required?:	Yes		
Target Superheat:	4 - 25°F		
Target Subcooling:	7°F		
Overall Result:	PASS		




Airflow

	<u>System #1</u>	<u>System #2</u>	<u>System #3</u>
Was this required?:	Yes		
Target Airflow:	350 CFM/ton		
Overall Result:	PASS		



Fan Efficacy

	<u>System #1</u>	<u>System #2</u>	<u>System #3</u>
Was this required?:	Yes		
Target Efficacy:	0.58 Watts/CFM		
Overall Result:	PASS		



Additional Notes

General Notes:	
Furnace(s) Notes:	
Air Conditioner(s):	
Duct Leakage Notes:	
Refrigerant Charge Notes:	
Airflow Notes:	
Fan Efficacy Notes:	